B-3351 - B-3358 1000-1048 Patapsco St. (West side) Baltimore, Md. Private access 1845-1855

The majority of houses along the west side of this block of Patapsco St. are small, two story, two bay wide gable-roofed brick houses built in the 1850's to provide inexpensive housing for the growing numbers of new workers arriving in the area, many of whom were recent immigrants. A number of these houses have recently been renovated and now serve a mixed commercial/residential use. 1000 Patapsco St. has been remodeled as a two story, shed roofed house with bracketed cornice; 1026 and 1042 Patapsco St. are two story plus attic, two bay wide brick houses. The houses along Patapsco St. were generally built by the owners of the houses located on the western sections of the lots, facing on S. Charles St.

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME				
HISTORIC				
AND/OR COMMON				
LOCATION				
STREET & NUMBER	1028-1038 Pataps	sco St.		
CITY, TOWN	Baltimore	. VICINITY OF	CONGRESSIONAL DISTR	СТ
STATE	Maryland			
CLASSIFIC	ATION			
CATEGORY	OWNERSHIP STATUS PRESENT USE		ENT USE	
DISTRICT	PUBLIC	x_occupied (1034,1036,1		_MUSEUM
* BUILDING(S)	X_PRIVATE	X_UNOCCUPIED (1038,1032	••	PARK
STRUCTURE SITE	_BOTH	X_WORK IN PROGRESS	_EDUCATIONAL	XPRIVATE RESIDEN
OBJECT	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS
_055201	IN PROCESSBEING CONSIDERED	YES: RESTRICTEDYES: UNRESTRICTED	GOVERNMENT	SCIENTIFICTRANSPORTATION
	BEING CONSIDERED	_ TES. UNNESTRICTED	_INDOSTRIAL	_ INANSPORTATION
OWNER OF	PROPERTY	_NO	MILITARY	OTHER:
OWNER OF	PROPERTY	_NO	20 Tangunata ataupa	_OTHER:
C	PROPERTY		lephone #:	3. 3 %
NAME		Te.	lephone #:	3. 3 %
NAME STREET & NUMBER CITY, TOWN		VICINITY OF	lephone #:	2. 1 g
STREET & NUMBER CITY, TOWN	32.27	VICINITY OF Li	lephone #: STATE, Z ber #:	ip gode
NAME STREET & NUMBER CITY, TOWN	OF LEGAL DESCR	VICINITY OF LII	lephone #:	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE.	OF LEGAL DESCR	VICINITY OF RIPTION Li Room 601	lephone #: STATE, Z ber #:	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE. REGISTRY OF DEEDS, E	OF LEGAL DESCR	VICINITY OF RIPTION Li Room 601	lephone #: STATE, Z ber #: lio #:	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE. REGISTRY OF DEEDS, E STREET & NUMBER CITY, TOWN	OF LEGAL DESCR ETC. Records Office Baltimore City Office	VICINITY OF RIPTION Room 601 Courthouse	lephone #: STATE, Z ber #: lio #:	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE. REGISTRY OF DEEDS, E STREET & NUMBER CITY, TOWN REPRESEN	OF LEGAL DESCR	VICINITY OF RIPTION Room 601 Courthouse	lephone #: STATE, Z ber #: lio #:	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE. REGISTRY OF DEEDS, E STREET & NUMBER CITY, TOWN	OF LEGAL DESCR ETC. Records Office Baltimore City Office	VICINITY OF RIPTION Room 601 Courthouse	lephone #: STATE, Z ber #: lio #:	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE. REGISTRY OF DEEDS, E STREET & NUMBER CITY, TOWN REPRESEN	OF LEGAL DESCR ETC. Records Office Baltimore City Office	VICINITY OF RIPTION Li Fo Room 601 Courthouse	lephone #: STATE, Z ber #: lio #: STATE Maryland 212	ip gode
STREET & NUMBER CITY, TOWN LOCATION COURTHOUSE. REGISTRY OF DEEDS, E STREET & NUMBER CITY, TOWN REPRESEN TITLE	OF LEGAL DESCR ETC. Records Office Baltimore City Office	VICINITY OF RIPTION Li Fo Room 601 Courthouse	lephone #: STATE, Z ber #: lio #:	ip gode

CONDITION

CHECK ONE

CHECK ONE

X EXCELLENT (1036,1034) DETERIORATED (1032,1038) XUNALTERED (1038,1028 ORIGINAL SITE __RUINS

XALTERED (rest)

__MOVED

 $x_{GOOD}(1030)$ X_FAIR (1028)

_UNEXPOSED

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This group of six two story brick houses with gable roofs was built in the 1850's. The houses are extremely small in scale. Several have recently been renovated with the first floor areas serving as store-fronts. Others are currently in the process of renovation.

The houses are two stories in height, range in width from about 11' wide to 14' wide, and occupy lots ranging in depth from 51' to 54 1/2' deep. house is two small rooms deep. Each house seems originally to have had a one story high, two bay deep rear addition. These survive at 1028 and 1030 Patapsco; 1032 has no rear additions and at this point in time, no rear wall at all; 1034 has a new one story high, two bay deep addition; 1036 has a new one story high, one bay deep addition; and 1038 has a new two story high, two bay deep addition. The houses are constructed in common bond, but 1030 Patapsco has a new facade of running bond and 1032 Patapsco is covered with formstone. The low-pitched gable roofs have two-tier brick cornices. 1028 Patapsco has single chimneys located on both the front and rear roof gables along the south side of the house; 1030 and 1032 Patapsco share a paired rectangular chimney located at the peak of the gable roof; 1034 Patapsco has a single chimney located along the rear roof gable on the south side of the house; and 1036 and 1038 Patapsco share a double hooded chimney located along the partition wall between the two houses on the rear roof gable.

1028 and 1034 Patapsco currently have no lintels on the window openings; 1030 Patapsco, which has a new brick facade has vertical stretcher lintels on the first floor windows and no lintels on the second floor windows; 1032 is covered with formstone so the original treatment of the lintels is hidden; 1036 and 1038 have splayed brick lintels on the first floor windows and flat wood lintels on the second floor windows. All of the sills on all of the houses are wood. The window openings of 1028, 1030, 1034, and 1036 are filled with new 6/6 double hung sash. 1032 has 1/1 double hung sash and 1038 currently has no sash, but when renovation is complete will also have new 6/6 sash. All of the houses originally had single light transoms. 1028 Patapsco has a glass and panel door, 1030 has a modern flush door; 1032 has a Mission-style door; and 1038 currently has no door. The first floor areas of 1034 and 1036 have been converted into store-fronts. At 1034 there are three new multi-light French-style doors, set beneath a plain wood siding cornice. At 1036 a panel door with multi-light section above, is set beneath a three-light transom in the northernmost bay. To the left there is a new bay window with multi-light sash. There are no basements, and all of the houses except for 1036-1038 are reached directly from the sidewalk. The entrances of 1036 and 1038 Patapsco are reached by one stone step each. A flat-roofed alleyway runs between 1036 and 1038 Patapsco and back under the northernmost bay of 1030 Patapsco.

The original floor plan of 1038 Patapsco is still intact (though currently undergoing restoration). The house is two rooms deep, the front room measuring

7 DESCRIPTION

CONDITION

CHECK ONE

CHECK ONE

_EXCELLENT

__DETERIORATED

__UNALTERED

_ORIGINAL SITE

_GOOD

_RUINS

.

__FAIR

__UNEXPOSED

MOVED DATE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

1028-1038 Patapsco, cont.

about 'x 'and the back room measuring about 'x '. A tightly winding staircase is located along the north wall between front and back rooms. A rear door led to a kitchen addition.

8 SIGNIFICANCE

Ц	_INVENTION	5 96 555/08 min	
	INDENTION		
COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
ART	ENGINEERING	MUSIC	THEATER
XARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
_ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
AR	EAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	
	ARCHEOLOGY-PREHISTORICARCHEOLOGY-HISTORICAGRICULTURE	ARCHEOLOGY-PREHISTORICCOMMUNITY PLANNINGARCHEOLOGY-HISTORICCONSERVATIONAGRICULTUREECONOMICS	ARCHEOLOGY-HISTORICCONSERVATIONLAWAGRICULTUREECONOMICSLITERATURE

STATEMENT OF SIGNIFICANCE

These houses are significant as being representative of a group of extremely modest two story, gable-roofed houses built in the 1850's and 1860's to serve as inexpensive housing for the influx of newly arrived immigrant families seeking work in harbor-related activities. Most of these houses were held as rental property and many were located along narrow alley streets, as is the case here. In terms of design, the houses are basically the descendants of earlier Federal-style working class housing built in the early decades of the century, but without the usual dormer story of such ouses. Because there is no dormer story the roof slope is less steep in these later versions of the style. The houses are quite tiny, with two small rooms on each floor and a centrally located, tightly winding, narrow staircase. Most of the houses have recently been renovated and turned into combination store-fronts/residences.

This group of houses was built by George L. Addison as part of his development of his property fronting along Charles St. (from 1033-1039 S. Charles St.), and by Henry Bachman, as part of his development of his property fronting on 1041-1043 S. Charles St. Bachman's houses (1036-1038 Patapsco St.) may actually have been constructed by Addison as he was building his row of four houses to the north. Like most such houses these were held by the owners of the corresponding lots on Charles St. as rental property.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _ 12'6" x 51' (1028); 14' x 51' (1030)' 13'6" x 51' (1032); 13' x 54'6" (1034); 10'9" x 54'6" (1036); 11'6" x 54'6" (1038)

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

1 FORM PREPARED BY

NAME / TITLE

M.E. Hayward / Historic Sites Surveyor

Maryland Historical Trust / Struever Bros. & Eccles STREET & NUMBER

a Eltrechinelli

DATE

2517

5/79 TELEPHONE

1745 Circle Rd.

STATE

CITY OR TOWN Ruxton

Maryland 21204

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

B - 3356

Date.

Form Approved OMB No 42-R1765



Signature .

Keeper of the National Register

UNITED STATES DEPARTMENT OF THE INTERIOR Heritage Conservation and Recreation Service Office of Archeology and Historic Preservation Washington D.C. 20243

HISTORIC PRESERVATION CERTIFICATION APPLICATION - PART 1

(Pursuant to the Tax Reform Act of 1976)

Instructions: Applicant should read the instructions carefully before completing application. No Certification may be made unless a completed application form has been received (P.L. 94-455). Use typewriter or print clearly in dark ink to complete the application form. If additional space is needed to complete Part 1, use the reverse side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropri-

ate State Historic Preservation Officer at any time during the year, and may be sent separately or with Part 2.
PART 1 EVALUATION OF SIGNIFICANCE
1. NAME OF PROPERTY: Children's Bookstore/Struever Residence
Address of property Street 1036 -1038 Patapsco Street
CityBaltimore
Name of historic district in which property is located: Federal Hill Historic District (National Register
2. DESCRIPTION OF PHYSICAL APPEARANCE: (See instructions for map and photograph requirements—use reverse side if necessary) 1036 - 1038 Patapsco St., was constructed c.1845. The buildings were originally row houses. They were renovated in 1977 and 1979 as a children's bookstore and a residence.
3. STATEMENT OF SIGNIFICANCE: (use reverse side if necessary)
1036 and 1038 Patapsco Street are significant to the Federal Hill Historic District because of their date of contruction; their architectural integrity, individually and part of the continuity of the street scape and the total urban fabric Date of construction (if known) c.1845
4. NAME AND MAILING ADDRESS OF OWNER:
Name Frederick & Nancy Struever
Street 1036 Patapsco Street,
City Baltimore, State MD. Zip Code 21230
Telephone Number (during day): Area Code (301), 332-1352 I hereby attest that the information I have provided is no the best of my knowledge, correct, and that I am owner of the property described above Signature Date 3-18-81
For office use only
For office use only The structure described above is included within the boundaries of the National Register historic district and Contributes Didoes not contribute to the character of the district.
The structure described above is included within the boundaries of the National Register historic district and Contributes 🗆 does not contribute to the character of
The structure described above is included within the boundaries of the National Register historic district and contributes does not contribute to the character of the district. The structure described above is included within the boundaries of the National Register historic district and contributes does not contribute to the character of the district. The structure described above is included within the boundaries of the National Register Criteria for Evaluation (36 CFR 60.6) and district will not be nominated to the National Register in accord with Department of the Interior procedures (36 CFR 60). The structure is located in a district which dispers does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6), will likely will not be nominated to the National Register in accord with Department of the Interior procedures (36 CFR 60), and dispers does not appear to contribute to the character of said
The structure described above is included within the boundaries of the National Register historic district and contributes does not contribute to the character of the district. The structure described above is included within the boundaries of the National Register historic district and contributes does not contribute to the character of the district. The structure described above is included within the boundaries of the National Register historic district and contributes does not appear to the National Register in accord with the Department of the Interior procedures (36 CFR 60). The structure is located in a district which department of the Interior procedures (36 CFR 60), and despetation (36 CFR 60.6), will likely despetation to the Character of said the National Register in accord with Department of the Interior procedures (36 CFR 60), and despetation appears to contribute to the character of said the National Register in accord with Department of the Interior procedures (36 CFR 60), and despetation (36 CFR 60.6).
The structure described above is included within the boundaries of the National Register historic district and contributes does not contribute to the character of the district. The structure does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6) and will likely will not be nominated to the National Register in accord with the Department of the Interior procedures (36 CFR 60). The structure is located in a district which appears does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6), will likely will not be nominated to the National Register in accord with Department of the Interior procedures (36 CFR 60), and appears does not appear to contribute to the character of said district. Signature

1036 Patapsco St. is a brick, two story, two bay structure with a pitched roof. The brick is common bond. Before renovation, the brick was painted; the paint was severely deteriorated and peeling. The first floor comprises — a wood six panel door with a transom which was boarded; and one, one over four, wood frame sash window with the wood sills. The second floor had two, one over six wood frame sash windows with wood sills which were covered with a vinyl material. The glazing patterns were the result of repairs and were not the original configurations. The door and windows were unrestorable. 1038 Patapsco Street was similar in appearance and condition to 1036. The buildings were adapted new uses; the Children's book store on the first floor of both houses; a small office for the store on the second floor of 1036; and an apartment on the second floor of 1038. The buildings were sensitively altered, retaining their residential appearance. The structures were chemically cleaned and repointed. The mortar joint matches the original in dimension, profile and color.

1036 Patapsco Street now comprises the following:

On the first floor there is a glass and panel wood front door with a transom above; the door has nine panes and four wood panels below; the three pane transom has been reglazed; above the transom is a splayed brick soldier coarse lintel. The first floor window has been converted into a wood frame twenty pane cabinet window, which extends one pane from the facade. The second floor windows have been restored and now comprise six over six wood frame sash windows with wood louvered operable shutters; the wood sills have been restored. The facade has a simple brick cornice. Because the two buildings have been connected at the first floor level the passageway between the two structures has been closed off. The closure has been recessed approximately two feet to retain the appearance of the passageway; a simple wrought iron gate has been installed in the entrance.

1038 Patapsco Street comprises two sixteen pane wood frame cabinet windows on the first floor and two six over six wood frame sash windows with wood louvered operable shutters and wood sills on the second floor. There is a simple brick cornice. The brick used to fill in the former doorway on the first floor closely matches the original brick of the facade. The side (south elevation) abuts a newly paved and landscaped alley installed by the City to connect Patapsco Street to South Charles Street. Two wood frame oriel display windows have been installed on this elevation.

The earlier wood frame additions were deteriorated, removed, and reconstructed in masonry covered with stucco. The south elevation comprises—a wood frame oriel display window on the first floor, and a small greenhouse window on the second floor. The rear (west elevation) comprises—a wood frame with single glass pane french door, and a wood sidelight on the first floor; and wood frame multi-pane french doors with a side light on the second floor; and a six over six wood frame sash window with brick sills on the second floor. Off the second floor is a small wood deck with iron railings and wood steps; the deck is supported by wood posts.

The rear (west elevation) of 1036 comprises a one story, masonry covered with stucco addition, with a shed roof: The first floor has a wood four panel door with 4 lights at the top, and a wood frame, one over one sash window with iron bars; the second floor level is the original brick rear wall, painted red, with a wood frame one over one sash window with iron bars; there is an air conditioning unit on the shed roof.

IF NEEDED USE THIS SIDE TO COMPLETE ANSWERS TO PART 1

Description of Physical Appearance: CONT.

The interior of 1036 comprises two rooms for retail sales on the first floor and two rooms for an office on the second floor. The first floor front room has displayed shelves for books, stuffed animals and small toys; the original brick fireplace; and carpeted floors. The first floor rear room has shelves; a window seat; and wood floors. The interior of 1038 comprises two rooms for retail sales and storage on the first floor and an apartment of three rooms on the second floor. The first floor front and rear rooms contain shelves and cabinets to display the merchandise; window display shelves created by the oriel windows; and carpeted floors. The second floor comprises front bedroom with exposed original rafters; a hall and bathroom; and a rear kitchen.

Statement of Significance: CONT.

and character of the neighborhood; and their creative and sensitive adaptive use for commercial purposes.


The Federal Hill Historic Dictrict was shaped by the expansion of the City, south into the peninsula, which was annexed to the City in 1816; the early and later industrialization into the area, including the mining of sand, clay and iron; shipping; shipbuilding and the development of related businesses; construction of railroad lines to the port areaswhich further stimulated industrial development of the port and the City; immigration, primarily the Irish and Germans; and the later migration of farmers into the City after the Civil War. The South Baltimore peninsula was laid out in a grid pattern. Development spand the 19th century through the early 20th century. As the area developed diverse economic groups lived together; professional and wealthie citizens lived on the main streets in larger houses. Laborers, artisans, and free blacks lived on small streets and alley streets in more modest dwellings, like those at 1036 and 1038 Patapsco Street. These two row houses were built c. 1845, as part of the first wave of residential development. The occupants of these houses were probably immigrants or free blacks. The Irish were unskilled laborers and worked primarily on the construction of the railroad and later in the packing and canning factories around the harbor. The Germans were skilled workers and were employed as cabinet makers and machinists. The free blacks were also unskilled and worked as stevedores and vendors and in the service industries, serving as cooks, tailors and butchers. Architecturall these houses were typical of those constructed from the early to mid 19th century throughout the City. These small structures were vernacular adaptations of the Federal style. This building style is the earliest housing type found in South Baltimore. There are a few such structures built in wood, most of these have been covered with asbestos shingles or form stone. Wood construction was band in Baltimore early/19th century to prevent fires. Through the 19th century this style evolved into the large three story rowhouse. First dormer windows were added; next a small third floor with eyebrow windows, was built; and later the full third story was constructed, creating the optimum ·Urban Housing form. Rows of houses developed early in the city's history to make the best use of valuable urban land.


IF NEEDED USE THIS SIDE TO COMPLETE ANSWERS TO PART 1

Statement of Significance: CONT.1


South Baltimore developed into a self-contained urban neighborhood. Cross and Light Streets became the business and commercial sections; the remaining streets were filled in with residential dwelling units. The boundaries of neighborhood development were created by the harbor to the north, the railroad to the west, and the spring garden gas works to the south. Construction of the Cross Street Market in 1845 responded to the growth and population of South Baltimore. The development of the neighborhood was complete by the 1920's. South Baltimore began to decline in the 1960s when plans were announced to demolish a large section of the neighborhood for the construction of a major inner-state highway. Many residents and businesses left the area and small houses like 1036 and 1038 Patapsco Street fell into disrepair for lack of maintenance. By the late 1960's preservationists had purchased many of the buildings, listed the area impacted by the proposed highway on the National Register of Historic Places, and took legal action against local and federal governments to prevent the construction of the road. By the mid-1970's the restoration of the residential area was well underway; and revitalization of the commercial streets soon followed.

1036 and 1038 Patapsco Street are integral components of the architectural continuity of the neighborhood. The rehabilitation of these buildings responded to the changes in the land use around the Cross Street Market. To promote a stronger commercial base in South Baltimore, the City encouraged adapting the small residential into structures for retail uses. 1036 was rehabilitated in 1977 as the Children's Book Store, with an office for the store on the second floor. In 1979 the store expanded into 1038, the adjacent structure to the south, and an apartment was constructed on the second floor. These structures received the Mayor's Award for best rehabilitation in South Baltimore. The adaptive use of these buildings has stimulated other commercial use along Patapsco Street; to include gift shops, blacksmith's showroom, and a lock smith. The commercial revitalization of the Federal Hill Historic District is probably the most successful of all of the city's commercial endeavors, in terms of the quanity of adaptive use and the quality of the rehabilitation with respect to preserving the architectural integrity and continuity of the neighborhood.





May 1977 136 Patapace St.



Washington D.C. 20243

OMB No. 42-41/65

B - 3356





HISTORIC PRESERVATION CERTIFICATION APPLICATION — PART 1

(Pursuant to the Tax Reform Act of 1976)


Instructions: Applicant should read the instructions carefully before completing application. No Certification may be made unless a completed application form has been received (P.L. 94-455). Use typewriter or print clearly in dark ink to complete the application form. If additional space is needed to complete Part 1, use the reverse been received (P.L. 94-455). Use typewriter or print clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the approprisite or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropriate the second part of the part 2.

ate State Historic Preservation Officer at any time during the year, and may be sent separately or with Part 2.
PART 1 EVALUATION OF SIGNIFICANCE
1. NAME OF PROPERTY: 10:30 PATAPSCD
Address of property: Street 1030 PATIAPSCO FEDERAL HILL MD
City_BALTO CountyState_MACYLAND zip Code
City
Name of historic district in which property is located:
2. DESCRIPTION OF PHYSICAL APPEARANCE: (see instructions for map and photograph requirements—use reverse side if necessary)
(see instructions for map and photograph requirements
3. STATEMENT OF SIGNIFICANCE: (use reverse side if necessary) This is a typical ARTISIAN OF WORK IND CLASS GALTIMOCE (use reverse side if necessary) This is a typical ARTISIAN OF WORK IND CLASS
Kitchen and built in Federal Hill in 1855.
KITCHEL MADOLITION TO THE MADE
Date of construction (if known): 1855 XOnginal site Moved Date of alterations (if known): 1946 - 98
Name MICHAEL VINCE, ROBERT HISMERT, ALBERT HISMERT
Street 1529 CITY Spacks State MD Zip Code 21152
Telephone Number (during day): Area Code 361 - 377 - 2222
Telephone Number (during day): Area Code
I hereby attest that the information I have provided as, to the best of my knowledge, correct, and that I am owner of the property described above.
Signature Mark 70 mm Date 9 9
For office use only The structure described above is included within the boundaries of the National Register historic district and Contributes (I) does not contribute to the character of
the district. The structure \Box appears \Box does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6) and \Box will likely \Box will not be nominated to the National The structure \Box appears \Box does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6) and \Box will likely \Box will not be nominated to the National
Register in accord with the Department of the limited papers of the structure is located in a district which appears of does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6), will likely will not be nominated to the National Register in accord with Department of the Interior procedures (36 CFR 60), and appears does not appear to contribute to the character of said nated to the National Register in accord with Department of the Interior procedures (36 CFR 60), and appears does not appear to contribute to the character of said
district. Date 12-31-51
State Historic Preservation Officer
This property has been evaluated according to the criteria and procedures set forth by the Department of the Interior (36 CFR 67) and, if subject to depreciation uncer
167 of the Internal Revenue Code of 1954.
Is hereby certified a historic structure I is hereby certified a historic structure I does not contribute to the character of the historic district and does not ment certification as a historic structure. Reasons given on the attached sheet.
Date
Signature Keeper of the National Register







B-3356



11




FEDERAL HILL NATIONAL REGISTER HISTORIC DISTRICT 4/17/70



CHARLES

CROSS STREET MARKET

B-3356 1028-1038 Patapsco Street Block 0934B Lots 045-050 Baltimore City Baltimore East Quad.





B-3356 1028-1038 Patapsco
M.E.H. 4/79

East elevation